

СПИСОК ДЕТАЛЕЙ ДЛЯ "STICKER, INTEGRAL BRAKE (FAILURES)" BMW K1200GT

//WWW.OEM.MOTO-ALL.RU/

ТЕЛ.: +7 (495) 177-12-75

1

BMW Integral ABS - Fault table			Order No. 01 41 7 663 591
General warning light 	ABS warning light  / brake failure	Malfunctions	
OFF	ON	Only RESIDUAL BRAKING FUNCTION available in both circuits.	
OFF	Flashes at 1 Hz	ABS not available Full-away test not completed.	
OFF	Flashes at 4 Hz	Only RESIDUAL BRAKING FUNCTION available in both circuits Self-diagnosis not completed.	
ON	OFF	Rear light brake light defective.	
ON	Flashes at 1 Hz	At least one brake circuits without ABS..	
ON	Flashes at 4 Hz	At least one brake circuits in RESIDUAL BRAKING FUNCTION mode	
Alternate flashing at 1 Hz	Alternate flashing at 1 Hz	Fluid level in BMW Integral ABS too low Check the motorcycle as follows. - Ignition Off; is brake pressure OK at the brake levers ? - Are the brakes acting on both wheels ? - Is the brake system leaktight, no signs of brake fluid escaping? The brake system is defective if the test outcome is negative.	
		 Warning: Do not ride the motorcycle if you have any doubts about the safety of the brake system.	

СПИСОК ДЕТАЛЕЙ ДЛЯ "STICKER, INTEGRAL BRAKE (FAILURES)" BMW K1200GT
//WWW.OEM.MOTO-ALL.RU/
ТЕЛ.: +7 (495) 177-12-75

№	№ OEM	наличие / срок поставки	Наименование	Кол-во в узле
01	01477663598	Срок поставки от 19 дней	BMW # 01477663598 (AUFKLEBER ST	1